

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number TXD008950461		2. Page 1 of 1		3. Emergency Response Phone (713) 906-7303		4. Manifest Tracking Number 013483775 JJK				
		5. Generator's Name and Mailing Address CES Environmental Services i/c/o David Aska State ID: 30900 4904 Gripps Road Houston, TX 77021 Generator's Phone:						Generator's Site Address (if different than mailing address) CES Environmental Services i/c/o David Askanase 4904 Gripps Road Houston, TX 77021				
6. Transporter 1 Company Name C4 Environmental Services, LLC.		State ID: 87955				U.S. EPA ID Number TXR000070243						
7. Transporter 2 Company Name						U.S. EPA ID Number						
8. Designated Facility Name and Site Address Lone Star Ecology 12901A Baypark Road Pasadena, TX 77507 Facility's Phone: (281) 204-1268		State ID: 50207				U.S. EPA ID Number TXD010791184						
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))				10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
			No.	Type								
	X	1. UN2810, Waste Toxic, liquids, organic, n.o.s. (Potassium Ferric cyanide, Hydrosulfide), 6.1, PGII				01	DF	10	P	FX9G001H 0002 0003		
	X	2. UN3093, Waste Corrosive liquids, oxidizing, n.o.s. (Hydrochloric acid, Nitric Acid), 8, PGII				25	OF	25	P	FX9G001H 0002 0001		
	X	3. UN1479, Waste Oxidizing solid, n.o.s. (Sodium dichlorothiazetrione, Trichlorotrizenetrione), 5.1, PGII				01	DF	10	P	FX9G001H 0001		
		4. <i>15 gal 35 gal 44 gal</i>										
14. Special Handling Instructions and Additional Information <i>1. 5 gal 1072 3. 5 gal 1072</i> <i>2. 14 gal 1072</i>												
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.												
Generator's/Offoror's Printed/Typed Name <i>David W. Wiegand</i>						Signature <i>David W. Wiegand</i>		Month Day Year <i>10 21 14</i>				
INT'L	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____											
	17. Transporter Acknowledgment of Receipt of Materials											
TRANSPORTER	Transporter 1 Printed/Typed Name <i>David W. Wiegand</i>						Signature <i>David W. Wiegand</i>		Month Day Year <i>10 21 14</i>			
	Transporter 2 Printed/Typed Name						Signature		Month Day Year			
DESIGNATED FACILITY	18. Discrepancy											
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection											
	Manifest Reference Number: _____											
	18b. Alternate Facility (or Generator) _____ U.S. EPA ID Number _____											
	Facility's Phone: _____											
	18c. Signature of Alternate Facility (or Generator) _____ Month Day Year _____											
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)												
1. <i>H141</i>			2. <i>H141</i>			3. <i>H141</i>			4.			
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a												
Printed/Typed Name <i>Joe McLaughlin</i>						Signature <i>Joe McLaughlin</i>		Month Day Year <i>10 22 14</i>				